
MARION COUNTY SURVEYOR'S OFFICE

DEBRA S. JENKINS MARION COUNTY SURVEYOR SECTION CORNER RECORD SEC. $10\,\text{Twn}$. $14_{\text{N}}\,\text{Rng}$. 5_{E}

BRYAN F. CATLIN, PLS TECHNICAL SUPERVISOR



Corner originally set as a post in 1820 by John Hendricks with the following witnesses: 12" beech bearing N 1 W 22 and a 6" dogwood bearing S 70 E 19. (M.C. Atlas p. 15) A survey by H.B. Fatout on March 18, 1878 indicates no stone or witnesses. (Franklin Legal Book p. 48) Corner referenced by Wilcoxen on 9/7/77 and called a r.r. spike. Corner excavated by Whitlock Surveying on 12/17/80 and a r.r. spike was found 1" down. An iron pin was set in place after digging to dirt. No stone was found. Corner referenced by Jacobs on 8/1/87 and called an iron pin 18" long. Corner referenced by Whiteside on 1/6/94 and called an iron pin found. Corner referenced by Wilcoxen on 4/26/00 and called an iron pin 2" down. Corner referenced by Wilcoxen on 1/6/05 and called an iron pin 2" down. Corner referenced by Greene on 4/15/09 and called an iron pin 2" down.

REF.	DISTANCE	DESCRIPTION
1.	116.90'	Nail in bottle cap N PwP #35-771 FA 6" up
2.	107.90'	Concrete block far East corner of 11945 Indian Creek
3.	36.70'	Mag nail w/brass washer set N 48" Hackberry 4" up
4.	119.03'	SE corner of concrete porch - 6432 Carroll Rd
5.	41.40'	Mag nail w/brass washer set E PwP #42-741 FB 24" up